

1.0 Reference and Address			
Report Number	101998351CRT-001 Ori	ginal Issued: 22-Mar-2016	Revised: None
	Standard for Safety for Hardware for the Support of Conduit, Tubing and Cable, UL 2239, Second Edition, Dated February 20, 2015.		
Standard(s)	Canadian Standard for Hardware for the Support of Conduit, Tubing and Cable, CAN/CSA C22.2 No. 18.4-15, Second Edition, Dated Februay 20, 2015 Standard for Safety for Positioning Devices, UL 1565, Fifth Edition, Dated January 25, 2013 Canadian Standard for Positioning Devices, CAN/CSA C22.2 No. 18.5-13, Second Edition, Dated January 25, 2013		
		on for the	Cambria County Association for the
Applicant	Cambria County Associati Blind & Handicapped	on for the Manufacturer	Cambria County Association for the Blind & Handicapped
Applicant Address	Cambria County Associati	Address	
	Cambria County Associati Blind & Handicapped 175 Industrial Park Road	Address	Blind & Handicapped   175 Industrial Park Road
Address	Cambria County Associati Blind & Handicapped 175 Industrial Park Road Edensburg, PA 15931-410	09 Manufacturer Address	Blind & Handicapped175 Industrial Park RoadEdensburg, PA 15931-4109
Address Country	Cambria County Associati Blind & Handicapped 175 Industrial Park Road Edensburg, PA 15931-410 USA	09 Address Country	Blind & Handicapped175 Industrial Park RoadEdensburg, PA 15931-4109USA
Address Country Contact	Cambria County Associati Blind & Handicapped 175 Industrial Park Road Edensburg, PA 15931-410 USA Allen Smith	D9 Address Country Contact	Blind & Handicapped175 Industrial Park RoadEdensburg, PA 15931-4109USAAllen Smith

Page 1 of 43

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.